

INDUSTRIAL RAILWAY SOCIETY PHOTOGRAPHIC SERVICE

KEVIN LANE COLLECTION; List no.2 (September 2018)

Available from: Kevin Lane, 15 Beech Green, Dunstable, Bedfordshire, LU6 1EB. Tel: 01582 601458

NCB, Coppice	28 COPPICE, 0.6.0ST (P1732/27), LH ¾ front view, 1950s	P7/38
NCB, Pinxton	PECKETT No.2, 0.4.0ST (P1975/39), RH ¾ front view, 1950s	P7/39
USC, Exton Park Quarries	11, 0.6.0ST (YE2568/54), LH ¾ front view with loaded train, 22/4/61	P7/42
	1357, 0.6.0ST (YE2501/51), LH ¾ rear view shunting full wagons over the weighbridge, 19/10/63	P7/44
	1352, 0.6.0ST (YE2568/54), LH ¾ front view with loaded train leaving Exton park for Ashwell sidings, 19/5/64	P7/45
	1362, 0.6.0ST (YE2484/50), LH ¾ front view with train at Exton Park weighbridge, 19/5/64	P7/47
	1354, 0.6.0ST (YE2573/54), LH ¾ front view with train from quarries at Exton Park, 19/5/64	P7/49
	1362 at the loco shed with 1354 passing with a loaded train, 19/5/64	P7/50
	1353, 0.6.0ST (YE2569/54), RH ¾ rear view, possibly OOU, 23/8/67	P7/51
USC, Cottesmore Mines	301, 0.4.0ST (Lysaght/46), LH ¾ rear view outside loco shed, 22/5/56	P7/57
	340, 0.6.0ST (KS3089/18), LH ¾ front view, 22/5/56	P7/58
Dorman Long, Burley Quarries	BERYL, 0.4.0ST (AB926/02), RH ¾ rear view, 22/5/56	P7/61
USC, Burley Quarries	170, JUPITER, 0.4.0ST (HL2604/05), RH broadside view, 15/4/61	P7/62
New Cransley Iron & Steel	NEW CRANSLEY No.3, 0.4.0ST CF1194/00), LH ¾ front view, 9/6/56	P7/66
USC, Colsterworth East	29, 0.6.0ST (MW1917/17), LH ¾ rear view, 19/4/60	P7/118
USC, Colsterworth North	38, 0.6.0ST (RSH7296/46), LH ¾ front view, 19/4/60	P7/119
	21, 0.6.0ST (HC1253/17), LH ¾ front view, 19/4/60	P7/120
NCB, Oxcroft	0.4.0ST (HE3289/45), LH ¾ front view, 8/3/64	P7/401
	No.1, 0.4.0ST (HL3631/25), RH ¾ front view, 8/3/64	P7/402
NCB, Ireland	0.6.0ST (WB2751/44), RH ¾ front view, 8/3/44	P7/407
NCB, Sutton	0.6.0ST (AB1132/07), LH ¾ front view, 31/5/66	P7/412
NCB, Markham	75021, 0.6.0ST (HE2870/43), RH ¾ front view, 8/3/64	P7/425
	27, 0.6.0ST (HE1708/35), RH ¾ front view OOU, 8/3/64	P7/426
	DL10, 0.6.0DH (YE2874/63), RH ¾ front view, 7/6/79	K7873
	DL2, 0.6.0DH (YE2839/62), LH ¾ front view, 7/6/79	K7877
	BR class 56 56028 passing under tippler with HAAs for loading, 7/6/79	K7884
Marlow Sand & Gravel	5, 4wDM (MR21283/65), RH ¾ front view at screens, 26/6/75	K2383
	3, 4wDM (MR7176/37), LH ¾ front view approaching screens with loaded train, 26/6/75	K2385
	Tipping wagons by hand at screens, 26/6/75	K2396
Herbert Morris, Loughborough	4wDM (MR4219/35), LH view, OOU in stockyard, 30/9/76	K3768
	4wDM (MR2026/20), RH view, OOU in stockyard, 30/9/76	K3772

Amey Roadstone, Loughborough	Ex-BR 0.6.0DE 3101, RH ¾ rear view shunting ballast empties. 30/9/76	K3775
Chemical & Insulating, Darlington	4wDM (RH375360/54), RH ¾ front view with empty v-skips at tip, 30/6/78	K6453
	4wDM (RH476124/62), RH near full front view near tip, 30/6/78	K6459
	4wWE (GEC/28), RH view shunting wagons up to tippler, 30/6/78	K6465
NCB, Bolsover	0.4.0DH (EEV D922/65), RH ¾ rear view shunting HAA wagons over weighbridge, 7/6/79	K7905
	D5, 0.6.0DE (RH425476/59), LH ¾ rear view amid a sea of wagons, 7/6/79	K7918
	Assorted narrow gauge wagons at pit head, 7/6/79	K7921
STWA, Newstead	4wDM (SMH104GO60/76), LH ¾ rear view propelling three V-skips of dried sludge for tipping, 8/6/79	K7937
	4wDM (SMH104GO60/76), RH ¾ front view, wagons being filled with dry sludge by Ford tractor with shovel, 8/7/79	K7646
	4wDM (SMH104GO63/76), LH ¾ rear view; in the background, two workman push a v-skip of dried sludge for tipping, 8/7/79	K7952
CEGB, Connah's Quay	1, 0.4.0DM (JF4210077/52), RH ¾ front view, 9/6/79	K7985
	1, 0.4.0DM (JF4210077/52), LH ¾ rear view shunting full wagons near tippler, 9/6/79	K7986
	Ex-BR/LMS brake van DM280322, 9/6/79	K7988
	2, 0.4.0DM (JF4210090/54), LH ¾ front view inside shed, fresh from overhaul, 9/6/79	K7990
Kingston Minerals, Monks Park Mine, Corsham	The driver of 4wDM (RH359169/53), RH ¾ rear view, positioning flat wagon on turntable, 4/80	KA5/3/4
	Flat wagon descending down into mine, 4/80	KA5/3/6
	4wDM (RH398101/56), LH ¾ front view, awaiting repairs to gearbox, 4/80	KA5/4/2
	4wDM (RH359169/53), LH ¾ front view, outside drum house with wagon containing slabs of stone newly arrived from the mine, 4/80	KA5/4/3
	4wBE (GB2920/58) inside mine, 4/80	KA5/4/4

KL-02